

Claas CELTIS 446RX | 2009

POA



Vehicle Features

Condition: Good, Drive Type: Mechanical, Engine Type: Engine
EGR, Front Tyre Size / Condition: 340/85/24 Agrimax 10%,
Loader, Loader Make: FL80, Pick Up Hitch, Rear Tyre Size /
Condition: 420/85/R34 10%, Road Speed: 40 KPH, Spools Rear: 2